

Ed Croskey Rec Center



Overview



Overview




Split in Membrane



Hole in Membrane




Hole in Membrane




Hole in Membrane



Hole in Membrane




Overview




Failing Previous Repairs



Holes in Roof



Holes in Roof



Holes in Membrane



Holes in Membrane



Holes in Membrane



Holes in Membrane



Core Cut



Core



Core Cut Showing Wet Deck



Core




Core Cut Repair



Hole in Membrane



Cap Sheet not Adhered to Metal Perimeter



Ponding Water



Ponding Water



Ponding Water