

CA:78 - site evaluation approved

v 12/86

(C)

STATE OF FLORIDA
DEPARTMENT OF STATE
Division of Archives, History
and Records Management
DS-HSP 3AAA

Rev 3-79

FLORIDA MASTER SITE FILE
Site Inventory Form

FDAHMRM 802 = =
1009 = =

1009 = =

Site No. 10- (51755) 2820-000-01

830 = = Survey Date 1981 820 = =

905 = =

Site Name _____

Address of Site: 507 S.E. Ft. King

Instruction for locating N. side middle Elk 500 S.E. Ft. King St.

813 = =

Location: Caldwells AD Ocala Com 40 Ft N & 105 Ft W of NE Cor Lot 13 868 = =

subdivision name

block no.

lot no.

808 = =

County: Marion - Thence W 105 Ft N 116 Ft N/105 Ft S 116 Ft

Owner of Site: Name: Whittle, Claude C & M L MONSEES, Thomas JOHN

WEST, CAROLYN H MONSEE

Address: 2092 NW 144th Ave. Rd. 300 SW 36 Pl Ocala 902 = =

Ocala, FL 32670

300 SW 36 Pl Ocala

902 = =

Type of Ownership Private 848 = = Recording Date 1981 832 = =

Recorder:

Name & Title: Withlacoochee Regional Planning Council, Joyce Cusick, Assoc.

Planner

Address: 1241 S.W. 10th St.

818 = =

Ocala, FL 32670

Condition of Site: Integrity of Site: Original Use Residence 838 = =

Check One

Check One or More

Excellent 863 = = Altered 858 = =

Good 863 = = Unaltered 858 = =

Fair 863 = = Original Site 858 = =

Deteriorated 863 = = Restored () (Date: X) 858 = =

Moved () (Date: X) 858 = =

Present Use Residence 850 = =

Dates: Beginning CA: 1888 844 = =

Culture/Phase American 840 = =

Period 845 = =

NR Classification Category: 916 = =

Threats to Site:

Check One or More

Zoning () () 878 = = Transportation (X) () 878 = =

Development (X) () 878 = = Fill (X) () 878 = =

Deterioration () () 878 = = Dredge () () 878 = =

Borrowing () () 878 = =

Other (See Remarks Below): 878 = =

Areas of Significance:

Architecture


910 = =

Significance:

An example of a Victorian frame vernacular style house exhibiting Colonial architectural influences. The house is in scale and character with its surroundings, a residential Victorian neighborhood which has evolved from the 1880's through the early 1900's.

911 = =

ARCHITECT _____ 872 = =
 BUILDER _____ 874 = =
 STYLE AND/OR PERIOD Victorian frame vernacular Colonial 964 = =
 PLAN TYPE central 966 = =
 EXTERIOR FABRIC(S) asbestos shingles 854 = =
 STRUCTURAL SYSTEM(S) wood frame 856 = =
 PORCHES front, left 942 = =
 FOUNDATION: brick pier 942 = =
 ROOF TYPE: gable 942 = =
 SECONDARY ROOF STRUCTURE(S): second floor balcony is roof of porch 942 = =
 CHIMNEY LOCATION: central interior ridge, rear interior 942 = =
 WINDOW TYPE: small pane 942 = =
 CHIMNEY: brick 882 = =
 ROOF SURFACING: asbestos shingles 882 = =
 ORNAMENT EXTERIOR: wrought iron balustrade on porch and balcony 882 = =
 NO. OF CHIMNEYS 2 952 = = NO. OF STORIES 2 950 = =
 NO. OF DORMERS --- 954 = =
 Map Reference (incl. scale & date) USGS Ocala West - #447 - 7.5 Min. - 1964 809 = =
 Latitude and Longitude: 800 = =
 Site Size (Approx. Acreage of Property): 833 = =



Township	Range	Section



Photographic Records Numbers _____

81N70#3 (2,14,17)

84N312#21(10)
Contact Print