
STATE OF FLORIDA DEPARTMENT OF STATE Division of Archives, History and Records Management

## FLORIDA MASTER SITE FILE Site Inventory Form

802 = = FDAHRM 1009 = = DS-HSP-3AAA 53957 Site No. 830 = = Survey Date 8303 820 = = Site Name 905 = =1244 S.E. 7th St Address of Site: \_\_ 1244 S.E. Instruction for locating \_ 813 = = Ocala, Fla. 32671 868 = = Oakleigh Park Ocala Lot 1 & E. 1/2 of Location: lot no. block no. subdivision name 808 = =Marion County: , JOHN W. SELPH Moring, Randall Owner of Site: Name: \_ Address: 1244 S.E. 7th St 902 = = Ocala, Fla. 32671 832 = =Type of Ownership \_\_Private 848 = = Recording Date Recorder: Name & Title: \_\_\_ Tate Susan (Preservation Architect) University of Florida - College of Architecture Address: \_ 818 = = Gainesville. 838 = = Residence Original Use \_ Integrity of Site: Condition of Site: Residence Check One or More 850 = = Check One Present Use 844 = = 858 = = ☐ Altered ☐ Excellent 863 = = Dates: Beginning C+ 1954 840 = = Culture/Phase \_\_\_\_American Good 863 = = Unaltered 858 = = 845 = =20th Century Period Original Site 858 = = Fair 863 = = Restored ( ) (Date: )( )858 = = Deteriorated 863 = = ☐ Moved ( ) (Date: )( )858 = = 916 = = NR Classification Category: \_ Building Threats to Site: Check One or More )( )878 = = ☐ Transportation ( )( -)( )878 = = )( )878 = = )( )878 = = ☐ FIII( )( □ Development ( )( Dredge ( )( )( )878 = = )( )878 = = Deterioration ( )( )( )878 = = ☐ Borrowing ( )( 878 = = Other (See Remarks Below): N.C. 910 = = Areas of Significance: \_ Significance: This residence was built in 1954 and is in Oakleigh Park Sub platted in 1929.

911 = =

		872 = =	
ARCHITECT		874 = =	
BUILDER	LIPIGITIC PERCHANGE AUBUST TERMS	964 = =	
STYLE AND/OR PERIODC	ontemporary Vernavular	966 = =	
PLAN TYPE	Rectangular		
EXTERIOR FABRIC(S)	Brick, wood novelty siding	854 = =	
STRUCTURAL SYSTEM(S)	Frame	856 = =	
RCHES	Front and rear	3.10.22235	
= × 1.10.	gdissels	942 = =	
FOUNDATION:	Continuous concrete	942 = =	
ROOF TYPE:	Gable	942 = =	
SECONDARY ROOF STRUCT	942 = =		
CHIMNEY LOCATION:	Left offset interior rear slope	942 = =	
WINDOW TYPE:	Wood DH, steel casement, fixed	942 = =	
CHIMNEY:	Brick	882 = =	
ROOF SURFACING:	Asphalt shingles	882 = =	
ORNAMENT EXTERIOR:		882 = =	
NO. OF CHIMNEYS	One 952 = NO. OF STORIES $T_{WO}$	950 = =	
NO. OF DORMERS	One sales we will be sales as a sales we will be sales as a sales with the sales are sales as a sal	954 = =	
Map Reference (incl. scale &	data) 1 10 seem were seem seems	sad loans	
Map Reference (Incl. Scale &	nakes wakad case as as as a case	809 = =	
Latitude and Longitude:	100 00 00 00 00 00 00 00 00 00 00 00 00	8000	
Latitude and Longitude.	1 11 0 1 11	800 = =	
Site Size (Approx. Acreage of Property):			



	3 1272 1372		
Township	Range	Section	sesio 9
15S .	22E	SE1/4 17	812 = =

UTM Coordinates:

Zone Easting Northing

Photographic Records Number 83 N 41 #9 (14,15)

Contact Print

