

CA 68: *exterior alterations (repair siding and paint)*

✓ 12/88 (old parcel #)
new parcel # 7/89
(C)

STATE OF FLORIDA
DEPARTMENT OF STATE
Division of Archives, History
and Records Management
DS-HSP-3AAA Rev. 3-79

FLORIDA MASTER SITE FILE

Site Inventory Form

FDAHRM 802 = =
1009 = =
Site No. (51912) 28362-039-01
Survey Date 8303 820 = =
905 = =

Site Name Marshall, William G. House 830 = =
Address of Site: 906 S.E. Ft. King St.
Instruction for locating 906 S.E. Ft. King St. 813 = =
Ocala, Fla. 32671 868 = =

Location: Caldwells Ad Ocala Com. at N.E. Cor. Lot 39; thence E. 1.48
subdivision name block no. lot no. 808 = =

County: Marion
Owner of Site: Name: (Florida 1st Natl. Bank Trust)
Address: Wodlinger, Beatrice, P. O. Box 370 902 = =
Ocala, Fla. 32678 832 = =

Type of Ownership Private 848 = = Recording Date _____
Recorder: _____

Name & Title: Tate, Susan (Preservation Architect)
Address: University of Florida - College of Architecture 818 = =
Gainesville, Fla. 32611 838 = =

Condition of Site: Integrity of Site: Original Use Residence 850 = =

- | | |
|---|--|
| Check One | Check One or More |
| <input checked="" type="checkbox"/> Excellent 863 = = | <input type="checkbox"/> Altered 858 = = |
| <input type="checkbox"/> Good 863 = = | <input checked="" type="checkbox"/> Unaltered 858 = = |
| <input type="checkbox"/> Fair 863 = = | <input checked="" type="checkbox"/> Original Site 858 = = |
| <input type="checkbox"/> Deteriorated 863 = = | <input type="checkbox"/> Restored () (Date: <input checked="" type="checkbox"/>) 858 = = |
| | <input type="checkbox"/> Moved () (Date: <input checked="" type="checkbox"/>) 858 = = |

Present Use Residence 850 = =
Dates: Beginning C+ 1906 844 = =
Culture/Phase American 840 = =
Period 20th Century 845 = =

NR Classification Category: Building 916 = =

- Threats to Site:
- | | | |
|---|---|---|
| Check One or More | | |
| <input checked="" type="checkbox"/> Zoning (<input checked="" type="checkbox"/>) | <input checked="" type="checkbox"/> () 878 = = | <input type="checkbox"/> Transportation (<input checked="" type="checkbox"/>) |
| <input checked="" type="checkbox"/> Development (<input checked="" type="checkbox"/>) | <input checked="" type="checkbox"/> () 878 = = | <input type="checkbox"/> Fill (<input checked="" type="checkbox"/>) |
| <input type="checkbox"/> Deterioration (<input checked="" type="checkbox"/>) | <input checked="" type="checkbox"/> () 878 = = | <input type="checkbox"/> Dredge (<input checked="" type="checkbox"/>) |
| <input type="checkbox"/> Borrowing (<input checked="" type="checkbox"/>) | <input checked="" type="checkbox"/> () 878 = = | |
| <input type="checkbox"/> Other (See Remarks Below): | 878 = = | |

Areas of Significance: Architecture 910 = =

Significance:

This classical revival house (wood) is an excellent example of this style, detailed with Ionic columns on the verandah porch, arched dormer window and shutters.

NOTE: Site condition: ashlar stone wall on North along Ft. King with ornamental gate at entry. Also, original base to hitching post for carriage on sidewalk

It is in Caldwells Ad Ocala platted in 1880 and first appears on the Sanborn Map of 1912.

It was the residence of William Marshall who owned and operated a plastering business in Ocala in the 1920's.


911 = =

chains S. 3.39 chains W. 1.48 chains N. 3.39 chains

ARCHITECT _____ 872 = =
 BUILDER _____ 874 = =
 STYLE AND/OR PERIOD Classic Revival 964 = =
 PLAN TYPE Central block - square 966 = =
 EXTERIOR FABRIC(S) Novelty clapboard 854 = =
 STRUCTURAL SYSTEM(S) Wood frame 856 = =
 PORCHES Verandah - North and West 942 = =
 FOUNDATION: Concrete block 942 = =
 ROOF TYPE: Gable/hip 942 = =
 SECONDARY ROOF STRUCTURE(S): Dormer - North 942 = =
 CHIMNEY LOCATION: Center 942 = =
 WINDOW TYPE: 1/1 wooden sash one arched - North 942 = =
 CHIMNEY: _____ dormer 882 = =
 ROOF SURFACING: Asphalt shingles 882 = =
 ORNAMENT EXTERIOR: Ionic porch columns, tracery brackets tongue & groove molding 882 = =
 NO. OF CHIMNEYS One 952 = = NO. OF STORIES Two 950 = = on eaves
 NO. OF DORMERS One 954 = =
 Map Reference (incl. scale & date) _____ 809 = =
 Latitude and Longitude: _____ 800 = =
 Site Size (Approx. Acreage of Property): _____ 833 = =

LOCATION SKETCH OR MAP N

S.E. Fort King Street



S.E. 2nd Street

Township	Range	Section
15S	22E	SE1/4 17

812 = =

TM Coordinates:

S.E. 10th Street
 Easting Northing

890 = =

Photographic Records Numbers

83N312 # 2 (11, 12)

Contact Print

