STATE OF FLORIDA

## FLORIDA MASTER SITE FILE

DEPARTMENT OF STATE	i comprime			
Division of Archives, Historian Records Management	? Site Inven	itory Form	FDAHRM	802 = =
DS-HSP-3AAA	Rev. 3-79	•	1-1921	1009 = =
		Site		
Site NameMorga	n, Mathew House	830 = 80	rvey Date	905 = =
Address of Site:	717 S.E. 6th St.			905 = =
nstruction for locating	g 717 S.E. 6th	St.		813 = =
	Ocala, Fla.	32671	4 5 7 7 7 25	868 = =
_ocation: <u>Caldwell</u> :	s Ad Ocala S. 1/2 of	E. 1/2 of W.	1/2 Lot 31	000 = =
	vision name	block no.	iot no.	= 808
Journey.		et research Paulo		- :
Owner of Site: Name	e: McNeal, Her 520 Lakemon	bert P.		
Address:	Winter Park	Fla. 32799		902 = =
Tupo of Ownorship	Private 848 = =	Recording Da	ite	832 = =
Recorder:	1111/406 515-			
	Tate, Susan (Preser	vation Archite	o+ )	;
Address:	Mark the control of t			
Audiess.	Gainesville Fla.		-Arenitteeture	818 = =
Condition of Site:	Integrity of Site:		A Dogiđenes	838 = =
Condition of Site.	integrity of one.	Original ou	Nebruchee	
Check One	Check One or More	Present Use	Residence	850 = =
Excellent 863 = =	X Altered 858	== Dates: Bed	inning <u>C+ 1895</u>	844 = =
Good 863 = =	☐ Unaltered 858	== Culture/Pha	seAmerican	840 = =
	✓ Original Site 858	D 3 - 1	19th Century	845 = =
Fair 863 = =			,	
Deteriorated 863 = =	Restored ( ) (Date: )( ) 858	= =		
	☐ Moved ( ) (Date: )( ) 858	<u> = =</u>		_
NR Classification Ca	ategory: Building		0	<u>916 = =</u>
Threats to Site:			16.	
Check On	e or More			
	)()878 = :	= Transportation	Х	)( )878 = =
		_		
Development ( )(	The state of the s	_		
Deterioration ( )(	)( ) 878 = :	= ☐ Dredge ( )(		)( )378 = =
Borrowing ( )(	)( )878=	<b>=</b>		
Other (See Remarks Bel	ow):	878 = =		
Areas of Significan	Architecture			910 = =

## Significance:

Areas of Significance: \_

Attractive one story gable roof wood frame vernacular L shaped with pitched roof porch.

Architecture

It is in Caldwells Ad Ocala platted in 1880 and first appears on the 1895 Sanborn Map.


This was the residence of Mathew Morgan, Chief of Police for Ocala in the early 1900's.

	872 = =			
	874 = =			
	964 = =			
Lahana	966 = =			
	854 = =			
7.7	856 = =			
TTONG	942 = =			
Brick niew	942 = =			
-	942 = =			
ROOF TYPE: Gable SECONDARY ROOF STRUCTURE(S):				
<del></del>	942 = =			
	942 = =			
	882 = =			
	882 = =			
ASDMAIT Shingles	882 = =			
952 - NO OF STORIES	950 = =			
Joz I I I I I I I I I I I I I I I I I I I	954 = =			
ta)				
	809 = =			
" • "	800 = =			
operty):	833 = =			
	West side 2/2 DHS Brick Asphalt shingles  952 == NO.OFSTORIES One			

Ν

## LOCATION SKETCH OR MAP S.E. 5th Street

S.E. Sanchez Ave.



S.E. 6th Street

Photographic Records Numbers \_ 83N418#14(23,24)

**Contact Print** 

Township	Range	Section	
15S	22E	SW1/4 17	812 = =

UTM Coordinates:

890 = = Northing Easting

