

CA 71 - rework

✓ 12/88

(old parcel #)
new parcel # 7189 (C)

PS1

STATE OF FLORIDA
DEPARTMENT OF STATE
Division of Archives, History
and Records Management

FLORIDA MASTER SITE FILE Site Inventory Form

DS-HSP-3AAA

Rev. 3-79

FDAHRM 802 = =

1009 = =

Site No. # (51771) 2820-021-005

Site Name Ausley, J.P. House 830 = = Survey Date 8303 820 = =

Address of Site: 620 S.E. Sanchez Ave. 905 = =

Instruction for locating 620 S.E. Sanchez Ave. 813 = =

Ocala, Fla. 32671 868 = =

Location: Caldwells Ad Ocala Lot 5 & E. 25' of Lot 4 Davidson Sub Lot 21.
subdivision name - block no. lot no.

County: Marion 808 = =

Owner of Site: Name: Stewart, Carlos MARY ANN S.

Address: 2907 S.E. 11th St. 902 = =

Ocala, Fla. 32671 832 = =

Type of Ownership Private 848 = = Recording Date

Recorder: Tate, Susan (Preservation Architect)

Name & Title: University of Florida - College of Architecture 818 = =

Address: Gainesville, Fla. 32611 838 = =

Condition of Site: Integrity of Site: Original Use Residence 850 = =

Check One

Check One or More

Excellent 863 = =

Altered 858 = =

Good 863 = =

Unaltered 858 = =

Fair 863 = =

Original Site 858 = =

Deteriorated 863 = =

Restored () (Date: X) 858 = =

Moved () (Date: X) 858 = =

Present Use Residence 850 = =

Dates: Beginning C+ 1912 844 = =

Culture/Phase American 840 = =

Period 20th Century 845 = =

NR Classification Category: Building 916 = =

Threats to Site:

Check One or More

Zoning (X) 878 = =

Transportation (X) 878 = =

Development (X) 878 = =

Fill (X) 878 = =

Deterioration (X) 878 = =

Dredge (X) 878 = =

Borrowing (X) 878 = =

Other (See Remarks Below): 878 = =

Areas of Significance: Architecture 910 = =

Significance:

The gable of this typical two story frame residence is detailed with ornamental wood shingles.

It is in Davidson Ad platted in 1889 and first appears on the Sanborn Map of 1912.

J. P. Ausley was the Branch Manager for Sinclair Oil Company in 1927.

911 = =

